

PURPOSE Regular.....1 Follow Up.....2 Complaint.....3 Other.....4		COUNTY OF FAIRFAX DEPARTMENT OF HEALTH SWIMMING POOL AND HEALTH SPA INSPECTION REPORT										1 of 2 4652						
Based on an inspection this day, the items circled below identify the violations of ¹ Code of the County of Fairfax, Chapter 69.1 ¹ Code of the City of Falls Church, Chapter 27.1 ¹ Code of the City of Fairfax, Chapter 22. All violations must be corrected by the next routine inspection or such shorter period of time as may be specified in writing by the Regulatory Authority on the reverse. A violation of the starred items may result in an order to suspend operations. See page 2 for legal notice of closure when applicable.																		
City Code	Est. #	Program Code	EHS ID	Date	M	M	D	D	Y	Y	TIME	H	H	M	Inspection Time	M	M	M
			58645		0	1	2	8	0	9	1:45							
ESTABLISHMENT NAME										OPERATOR'S NAME/POOL MANAGEMENT COMPANY								
Springhill Recreation Center										NV Pools, Inc. 14000E Thunderbolt Pl, Chantilly 20151 Tim Thomas 703-968-8800 FAX 703-730-6999								
ADDRESS										ZIP CODE								
1239 Springhill Rd. McLean, VA										22102-0000								
OWNER NAME/ADDRESS																		
Fairfax County Park Authority Joyce Quay, Aquatics Mgr.																		

I PERSONNEL AND SUPERVISION

		V	C
*01	Qualified operator present, on premises.	/	
*02	Lifeguards adequate in number, on duty.	/	
*03	C.P.R. certified person on duty.	/	
04	Licenses, permits, and certificates posted.	/	
05	Required signage posted.	/	
06	Accurate records kept.	/	

IV SAFETY AND SAFETY EQUIPMENT

		V	C
*23	Maximum load/usage numbers not exceeded Maximum number 274 (Pool) (Wading) 5 (Other) <i>SPA</i>	/	
24	Enclosure at proper height, non climbable, good repair, emergency gate kept clear. Access through bath house	/	
25	Underwater and deck lighting adequate/properly installed.	/	
26	Diving boards, slides, ladders, rails, steps in good repair, secure, properly maintained.	/	
27	Depth markings legible, properly located.	/	
28	Lifelines, lane markers, installed and in good repair.	/	
29	Reaching poles, and rescue tubes provided, positioned and in good repair.	/	
30	First aid kit provided, adequately supplied.	/	
31	First aid equipment: backboard w/ straps () blankets and cot () telephone accessible () No.	/	

II WATER QUALITY

		V	C
*07	Disinfectant Residual Adequate (Chemical <i>Cl</i>) + UV Light Residual: 4.0 (Main) (Wading) 8.0 (Spa) (Brown) (Other) (Other) (Other) /	/	
*08	Disinfectant level maintained through approved means.	/	
09	pH maintained at proper level. Readings: 7.4 (Main) (Wading) 7.4 (Spa) (Other) (Other) (Other) /	/	
10	Chemical test kit adequate, reagents supplied	/	
*11	Free of turbidity, debris, algae. No scum/grease line	/	
*12	Approved water supply, protected, free of cross connections	/	

III RECIRCULATION SYSTEM

		V	C
13	Skimmers: Basket, weir, adjustments. Overflow gutters. Water level	/	
14	Filter room cleanliness, ventilation, lighting, drainage.	/	
15	Filter room information placards posted.	/	
16	Hair and lint strainer, cleaned regularly.	/	
*17	Pump and motor properly maintained and operated.	/	
*18	Filter operated, maintained (Type:)	/	
19	Rate of flow indicator: properly installed, maintained. Readings: (g.p.m.) 150 (Main) (Wading) 100 (Other) <i>SPA</i>	/	
20	Gauges: properly installed, maintained. Readings: influent 15 (Main) (Wading) 6 (Other) <i>SPA</i> effluent: 8 vacuum: 9	/	
21	Vacuum cleaner approved. Built in () Portable ()	/	
22	Returns free flowing, adjustable, properly adjusted Dye test: approved () Disapproved () N/A ()	/	

V. POOL PREMISES

		V	C
32	Free of hazardous conditions, deck obstructions, metal and glass containers. Drain grates in place.	/	
33	Food confined to approved, separate dining area.	/	
34	Decks, coping in good repair, caulked, drained.	/	
35	White coat, interior finish in good repair, unstained.	/	
36	Grassed areas fenced, waist high showers at gates.	/	
37	General cleanliness maintained, approved refuse disposal, animals restricted.	/	

VI BATH HOUSES, LOCKER ROOMS, SHOWERS, TOILETS, ETC.

		V	C
*38	Adequate facilities, good repair, clean, sanitary, supplied.	/	
39	Ventilation: rooms free of condensation, odors, fungal growth	/	
40	Water heater, Anti-scalding devices, installed, adjusted	/	
41	Water fountains provided, maintained, adjusted	/	
42	Saunas, steam cabinets, in good repair, clean, disinfected	/	

Both Main pool and spas are compliant with VGB Act.

* Critical Items Requiring Immediate Attention
 V= Violation noted and needing corrective action
 C= Corrected action taken during inspection

Regular Inspection: Satisfactory () Closed () (See Page 2)

Received by: *Joyce Quay*

Environmental Health Specialist: *John Vander Voort*

John Vander Voort
 703-246-8413

SWIMMING POOL INSPECTION REPORT CONTINUATION FORM

Page 2 of 2

FAIRFAX COUNTY HEALTH DEPARTMENT
DIVISION OF ENVIRONMENTAL HEALTH
10777 MAIN STREET, SUITE 102
FAIRFAX, VA 22030



TELEPHONE (703) 246-8417
FAX (703) 278-8157
TDD (703) 591-6435

4652

ESTABLISHMENT NAME

Springhill Recreation Center (Fairfax County Park Authority)

MO

DAY

YR

01 28 09

ADDRESS

1239 Springhill Rd. McLean VA 22102-0000

VIOLATION DESCRIPTIONS/CORRECTIONS

✓ Last Routine Inspection Passed 10/16/2008
✓ Electrical Bond Insp. Passed 12/18/2008

★ Main pool is compliant with VGB Act. Has 3 main drains 24X24 with compliant grates

★ Spa pool is compliant with VGB Act. Has single recirculation circuit, served by 2-12X12 main drains with compliant grates. One is installed in bottom, one in a side wall, with grates than 3 foot separation

RECEIVED BY:

[Signature]
NAME

INSPECTED BY:

[Signature]
ENVIRONMENTAL HEALTH SPECIALIST
John Vander Voort 703-246-8413